

FIAT SERVICE LETTER

SUBJECT: BOSCH DISTRIBUTOR - ELECTRONIC BREAKERLESS
IGNITION

VEHICLES: 1979 X1/9 AND STRADA MODELS

**WARRANTY
INFORMATION**

When a Bosch Breakerless Distributor is found to be defective on a vehicle, which is still within the FMNA warranty period, the distributor must be replaced as a complete unit.

Do not attempt to perform any internal component replacements or repairs to the distributor under warranty, with the exception of replacing the distributor cap and rotor.

**WARRANTY CLAIM
PROCEDURE**

The proper warranty claim procedure for the replacement of a Bosch component is specified in Section C-5, of the Warranty and Adjustment Policy and Procedure Manual.

Warranty claims submitted for repairs or replacement of the internal components of the Bosch Breakerless Distributors will not be accepted for reimbursement.

**PARTS
INFORMATION**

The part numbers for the replacement Bosch Breakerless Distributors are as follows:

<u>MODEL</u>	<u>PART NO.</u>
X1/9	
49 State	4387801
California	4419074
Strada	
49 State	
w/o AC	4392844
w/ AC	4406490
California	
w/o AC	4419072
w/AC	4419073

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			