

FIAT SERVICE LETTER

SUBJECT: CYLINDER HEAD TORQUE

VEHICLES: ALL MODELS

GENERAL INFORMATION:

As specified by the Owners Warranty and Service Book, the cylinder head bolts must be properly torqued to Fiat specifications when performing the 1300/1800 Mile Service.

We must emphasize the importance of performing this operation in order to fulfill the complete maintenance requirements of the vehicle.

The tools necessary in performing this operation are as follows:

| <u>Model</u> | <u>Kent Moore Tool #</u> | <u>Fiat Tool #</u> |
|----------------|--------------------------|--------------------|
| 128-X1/9 | J 28032 | 50131 & 5013112 |
| 128 Front Bolt | J 28262 | 60392 |
| 124 Spider-131 | J 28033 | 50134 |
| 124 Spider-131 | J 28036 | 50149 |

All tools must be ordered through the Kent Moore tool program.

READ, INITIAL AND PASS ON

| Service Manager | Parts Manager | Service Writer | Technician | | | |
|-----------------|---------------|----------------|------------|--|--|--|
| | | | | | | |