

# FIAT SERVICE LETTER

SUBJECT: SPEEDOMETER CABLE  
VEHICLES: 124 SPORT SPIDER  
SERIAL NO.: STARTING WITH SERIAL NO. 137812

GENERAL INFORMATION:

A new speedometer cable has been installed on the above-mentioned vehicles. This new cable has been increased in length in order to eliminate the possibility of kinking or sharp bends.

The new speedometer cable can also be used as a replacement, if necessary, for both 1977 and earlier production 1978 vehicles.

PARTS INFORMATION:

The part numbers for both the complete and inner speedometer cables are as follows:

Complete Cable - #4419098  
Inner Cable - #4419099

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			