

FIAT SERVICE LETTER

SUBJECT: LICENSE PLATE LIGHT

VEHICLES: ALL MODELS

GENERAL INFORMATION:

In order to facilitate repairs instead of replacement of the complete license light assembly, the "Pig-tail" wire with insulator is now supplied as a spare part.

PARTS INFORMATION:

The part number of the pig-tail is as follows:


<u>Description</u>	<u>Part #</u>
Pig-tail	8044

WARRANTY INFORMATION:

When the repair is made, use the following operation number which includes R & R of light assembly.

Light socket "pig-tail" replacement-Oper. #554-01-40

In the future, replacement of the complete light assembly will not be accepted under warranty, if replacement of the "pig-tail" would have corrected the operation of the light assembly.



READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician