

FIAT SERVICE LETTER

SUBJECT: REMOVAL OF HAZE OR FILM FROM THE INSIDE SURFACE OF WINDSHIELDS AND OTHER GLASS

VEHICLES: ALL MODELS

CONDITION: An oily film or haze forming on the inside of the windshield and other body glass.

CAUSE: This film is caused by secretion of certain ingredients used in manufacturing of plastic interior components.

These ingredients and solvents are secreted especially when subjected to high ambient temperatures and then condense on the relatively cooler surfaces of the vehicle, such as the glass. The condition will diminish as these ingredients are bled from the plastic materials.

CORRECTION: The film may be removed by wiping the glass with regular household glass cleaner containing ammonia. Periodic cleaning is required and considered a normal maintenance function.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician			