

# **FIAT SERVICE LETTER**

SUBJECT: CONTROL IDENTIFICATION AND ILLUMINATION

VEHICLES: ALL MODELS

GENERAL INFORMATION:

Beginning with the 1973 models, Vehicle Safety Standard #S 101, deals with control location, identification and illumination

This means certain controls must be identified, properly located and illuminated. For instance, the vehicular hazard warning signal controls, windshields defrosting and defogging system controls, heating and air conditioning system controls, etc., must be illuminated.

When adding accessories, such as radios, air conditioning, etc. you must make certain the identification and illumination of the various controls are in proper working condition.

Make certain all controls requiring illumination are properly checked during P.D.I. Take corrective action if necessary, to be sure they are functioning properly before the car is placed in the consumer's hands.

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician